



บริษัท สยามโกลด์ลีฟ จำกัด  
Siam Gold Leaves Co., Ltd.

417/4 หมู่ 1 ตำบลปากพูน อำเภอเมือง จังหวัดนครศรีธรรมราช 80000  
โทรศัพท์ 0-7531-2315, โทรสาร 0-7531-3531  
417/4 Moo.1 Thumbon Pakpoon, Amphur Muang, Nakhonsrithammarat 80000

**STATEMENT OF COMPOSITION and IMPURITIES  
PRESENT IN 99.9+% GOLD FLAKES**

Prepared for: Cosmax USA  
65 Challenger Road Suite 130  
Ridgefield Park, NJ 07660

The following information is given, at the date of this document, to the best of our knowledge and/or according to laboratory testing results.

The 99.9+% GOLD FLAKES are produced from 1KG Swiss 99.99% gold bars. Lab tests of the gold bars show that the purity of the bars is 99.993% gold at the beginning of the manufacturing process. In the manufacturing process, a very small percentage of the purity is lost, thus reducing the GOLD FLAKES to a minimum of 99.9+% purity. It should be noted that the percentage of trace elements of each batch of GOLD FLAKES produced will never be the same, however, the percentage of gold will always be a minimum of 99.9+%.

The composition of the 99.9+% GOLD FLAKES including impurities are as follows:

NOTE: The below test results are from actual testing done with GOLD FLAKES submitted to a testing laboratory.

Composition:	99.989%	Gold (Au)*
	0.0095%	Silver (Ag)
	0.0014%	Copper (Cu)
	<0.0001%	Other*

\*Other elements tested (<0.0001%): As, B, Ba, Be, Bi, Cd, Ce, Co, Cr, Hg, In, K, Mg, Mn, Mo, Na, Nb, Ni, P, Pb, Pd, Pt, Sb, Se, Si, Sn, Sr, Ta, Te, Ti, Tl, V, W, Zn & Zr

Results in weight percent unless otherwise indicated.